

POPPLETON HISTORIC STUDY

B-2764

MAG 11#0427645404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
253	58-66	875-891 Lemmon Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on


<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
B	Quality-Indiv./groups-save	good fair poor bad
C	Important to street/groups	good fair poor bad
<u>D</u>	Insignificant/detrimental	good fair <u>poor</u> bad

Notable features:


These houses, plus the condition of 114-116 Parkin Street, blight the streets adjacent to them. Number 879 is formstoned and derelict.

Environmental context:

Lots (61-66) at 881-891 Lemmon Street have been cleared and 879 is vacant. Across-street two old houses stand alone among cleared lots. Would be better to clear this interior block; however, a word of caution, to wit, what holds up what: a structural analysis is needed to be sure that removing 875-877 Lemmon Street wouldn't be fatal to 114-116 Parkin.




Baltimore 1890 vol. 3, Sheet 83_a



B-2764

875-891 Lemmon Street (All but 877 demolished)

Sanborn Maps



B-2764
875-891 Lemmon Street (All but 877 demolished)
Block 0253, Lots 058-066
Baltimore City
Baltimore West Quad

